




Place a blinking beacon on the top and rear of the vehicle.



Use a truck-mounted impact attenuator on roads with a speed limit of 70km/h and above.



Secure the work zone before working along the road.



Place warning signs before securing the work zone.



DO NOT overload the vehicle and secure all loose debris.



Wear reflective vests when working along the road.



Visit www.wshc.sg for more information on Workplace Safety and Health.
Call the Ministry of Manpower hotline at 6317 1111 to report unsafe work practices.