



28 May 2021, Ref: 2122016

Accident Advisory: Worker caught in-between lift car and hoist way structure

Ref: 2021096 WSH Alert Accident Notification dated 3 March 2021

On 27 February 2021, a worker and his co-worker were tasked to carry out lift maintenance works. The worker was situated at the top of the lift car when it ascended and trapped him against a structure within the lift hoist way. The worker was subsequently extricated and pronounced dead at the scene by attending paramedics.

Read the full Advisory here.

Accident Advisory: Worker trapped between two shipping containers

Ref: 2021096 WSH Alert Accident Notification dated 3 March 2021

On 21 February 2021, a worker was walking along a path between two shipping containers in a stockpile yard when one container (retrofitted into a rest area) suddenly moved, trapping him. The injured worker was subsequently pronounced dead at the scene by attending paramedics.

Read the full Advisory here.

Accident Advisory: Worker pinned by toppled forklift

Ref: <u>2021094</u> WSH Alert Accident Notification dated 17 February 2021

On 20 February 2021, a worker was operating a forklift at a work site when he reversed it into a hacked pit. The forklift toppled and pinned him. The worker was subsequently rescued and conveyed to the hospital where he succumbed to his injuries.

Read the full Advisory here.

Accident Advisory: Worker fell off pilot ladder into sea

Ref: <u>2021094</u> WSH Alert Accident Notification dated 26 February 2021

On 16 February 2021, a worker was disembarking a vessel to board a passenger launch via a pilot ladder. While descending the pilot ladder, the worker fell into the sea. The worker was rescued and conveyed to the hospital where he was subsequently pronounced dead.

Read the full Advisory here.

Accident Advisory: Company director fell through floor opening

Ref: 2021092 WSH Alert Accident Notification dated 17 February 2021

On 10 February 2021, a company director was at a private dwelling overseeing construction work when he fell through a floor opening and landed on a staircase about 4.7m below. The injured director was pronounced dead at the scene by attending paramedics.

Read the full Advisory <u>here</u>.

Accident Advisory: Worker fell from cargo on trailer

Ref: 2021091 WSH Alert Accident Notification dated 10 February 2021

On 2 February 2021, a prime mover driver was standing on some steel bars on his trailer bed assisting a forklift operator to adjust a steel bundle when he fell about 2m to the ground. The injured driver was conveyed to the hospital where he succumbed to his injuries.

Read the full Advisory here.

Accident Advisory: Worker found unconscious on boom lift

Ref: 2021091 WSH Alert Accident Notification dated 10 February 2021

On 1 February 2021, a plasterer was found unconscious and slouched against the control panel of his boom lift. He was subsequently rescued and conveyed to the hospital where he was pronounced dead.

Read the full Advisory here.

We regret that we are unable to reply to emails at this email address. For enquiries or feedback, please email us at contact@wshc.sg.

Visit the WSH Council's website now for updates on WSH-related matters, information and events.



This WSH Bulletin is available free of charge, may be printed or downloaded onto electronic, optical or similar storage media provided that such activities are for private research, study, or in-house use only. If such material is to be copied or reproduced, users are asked to ensure that the material is reproduced accurately and not in a misleading context, that the status of the material is identified and to acknowledge Workplace Safety & Health Council, Singapore as the source of the material.