View in browser Ref: 2122154

March 2023



## **FATAL ACCIDENT**

their safety measures.

following measures or checks:


## On 26 February 2023, a worker was preparing to carry out water-proofing works on the roof of a

Worker dies after falling from roof

factory when he fell 4.1 metres to the ground. He was sent to the hospital but died of his injuries on 1 March 2023.

worker was not wearing a safety harness or a safety helmet at the time of the accident.

Preliminary investigations revealed that a horizontal lifeline was installed on the roof, but the



companies doing work at height to ensure worker safety and undertake an urgent assessment of

What companies should do Companies should urgently assess and ensure that their WSH management system includes the


• Fall Prevention Plan (FPP): Establish and implement a site-specific FPP to reduce the risk of falling from height when working on roofs.

• **Permit-to-Work (PTW) system:** Put in place a PTW system for work activities where a person

- could fall more than three metres. Ensure on-site checks are carried out by a competent person and risk controls are confirmed effective before authorising the work at height. • Safe Work Procedure (SWP): Develop a SWP for carrying out the task on the roof, taking into
- duration and frequency of work. Provide supervision to ensure the SWP is strictly followed. • Open side guarding: Install temporary guardrails or erect a scaffold platform with guardrails, if feasible, to prevent workers from falling off a roof edge.

account the roof's characteristics (e.g. material of construction, profile, and angle of slope) and the

**Guard rails** 



• Personal Protective Equipment (PPE): Equip roof workers with anti-slip safety footwear and fall-

arrest or travel-restraint equipment along with secure anchor point(s) or lifeline.

is too short, the use of an immediate arrest self-retracting line is recommended.


Anchorage

Self-retracting lifeline

Full body harness

Note that the use of a standard lanyard with a shock absorber cannot be used if the fall clearance

distance is too short to safely stop one's fall before striking the ground. If the fall clearance distance



During the extended Heightened Safety Period (1 September 2022 to 31 May 2023), the Ministry of Manpower will impose severe actions for serious WSH lapses, which include: Debarment from hiring new work pass holders.

Company leaders to personally account to MOM and take responsibility for rectifications, and

Engaging external auditors to conduct a thorough review of company's WSH processes.

Under the WSH Act, first-time corporate offenders may be sentenced to the maximum fine of

imprisonment not exceeding 2 years. Read more on the WSH Act penalties.

\$500,000 whilst individuals can either be sentenced to the maximum fine of \$200,000 and/or an


**Share this WSH Alert** 

Resources

attend a mandatory half-day in-person WSH training course.


\*Information on the accident is based on preliminary investigations by the Ministry of Manpower as at 6 March 2023. This may be subject to change as investigations are still on-going. Please also note that the recommendations provided here are not exhaustive and they are meant to enhance workplace safety and health so that a recurrence may be prevented. The information and recommendations provided are not to be construed as implying liability on any party

nor should it be taken to encapsulate all the responsibilities and obligations under the law.



Tripartite Alliance for

Workplace Safety and Health



Connect with us


**Events** 

on Workplace

Safety and Health

JOIN THE NATIONAL WSH CAMPAIGN 2022





<u>Subscribe</u> | <u>Unsubscribe</u> | <u>Update profile</u>